



缓冲式变减速机外型尺寸表

單位 : m/m

Size Dimensional Data of Buffered Reducer

型式 Type	使用馬力 Hores power applied HP	緩衝式變速機規格 Specifications for Buffer Variators												緩衝式變速機規格 Specifications for Buffer Variators										
		A	B	C	D	E	F	G	H	I	J	K	L	O	P	Q	R	S	T	U	V	W	X	Z
PH-402	½-1½	300	300	200	180	310	116	85	95	130	180	90	148	14	64	136	60	8	16	180	34 A2	100	60 B3	11
PH-403	2-3	360	320	230	200	310	132	115	100	155	203	110	160	16	78	159	60	8	14	215	51 A3	127	60 B3	11
PH-405	3-5	420	350	265	210	360	145	120	115	175	225	131	189	22	88	178	70	12	12	254	60 B3	127	60 B3	14
PH-410	7½-10	480	400	285	240	500	165	143	132	200	265	155	222	30	95	201	80	20	20	300	60 B3	150	90 C3	14
PH-415	10-15	580	480	340	270	500	202	163	147	260	315	195	250	30	115	241	105	20	30					17

PH-402 型變速機

變速數	變速比 Rate of Variation	出力軸回轉數參考表 Number of Turning Rounds for the Output Axis.	
		入力軸回轉數最高850轉 850 Turning Rounds, highest for the Input Axis.	入力軸回轉數最低500轉 500 Turning Rounds, highest for the Input Axis.
0	0	0	0
1	0.5	425 R. P. M	250 R. P. M
2	0.85	722 R. P. M	425 R. P. M
3	1.25	1,062 R. P. M	625 R. P. M
4	2.0	1,700 R. P. M	1,000 R. P. M

備註 使用馬達 ½Hp~1½Hp變速機重21kg

PH-403 型變速機

變速數	變速比 Rate of Variation	出力軸回轉數參考表 Number of Turning Rounds for the Output Axis.	
		入力軸回轉數最高850轉 850 Turning Rounds, highest for the Input Axis.	入力軸回轉數最低500轉 500 Turning Rounds, highest for the Input Axis.
0	0	0	0
1	0.5	425 R. P. M	250 R. P. M
2	0.9	765 R. P. M	450 R. P. M
3	1.4	1,190 R. P. M	700 R. P. M
4	2.0	1,700 R. P. M	1,000 R. P. M

備註 使用馬達 2Hp~3Hp變速機重31kg

PH-405 型變速機

變速數	變速比 Rate of Variation	出力軸回轉數參考表 Number of Turning Rounds for the Output Axis.	
		入力軸回轉數最高750轉 850 Turning Rounds, highest for the Input Axis.	入力軸回轉數最低400轉 500 Turning Rounds, highest for the Input Axis.
0	0	0	0
1	0.5	375 R. P. M	200 R. P. M
2	0.85	637 R. P. M	340 R. P. M
3	1.25	937 R. P. M	500 R. P. M
4	1.8	1,350 R. P. M	720 R. P. M

備註 使用馬達 3Hp~5Hp變速機重43kg

PH-410 PH-415 型變速機

變速數	變速比 Rate of Variation	出力軸回轉數參考表 Number of Turning Rounds for the Output Axis.	
		入力軸回轉數最高750轉 750 Turning Rounds, highest for the Input Axis.	入力軸回轉數最低300轉 300 Turning Rounds, highest for the Input Axis.
0	0	0	0
1	0.5	375 R. P. M	150 R. P. M
2	0.8	600 R. P. M	240 R. P. M
3	1.2	900 R. P. M	360 R. P. M
4	1.6	1,200 R. P. M	480 R. P. M

備註 使用馬達 7½Hp~10Hp變速機重72.5kg
10H~15HP